

Inspection Photos

Loc#335692

PAs/ALs

Operator: Encana

Inspection Number: 692401510

Inspection Date: 10/15/19






Photo#1:
Overview of Location to Northeast.

October 15, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PAs -ALs Loc#335692



Photo#2:
Evidence of Wells remains on site.




Photo#3:
Evidence of Wells remains on site.

October 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PAs -ALs Loc#335692



Photo#4:
Evidence of Wells remains on site..



Photo#5:
Evidence of Wells remains on site.

October 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PAs -ALs Loc#335692