

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2019

Submitted Date:

10/22/2019

Document Number:

692401510

**FIELD INSPECTION FORM**

Loc ID 335692	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b>  <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 2 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b>  OGCC Operator Number: 100185  Name of Operator: ENCANA OIL & GAS (USA) INC  Address: 370 17TH ST STE 1700  City: DENVER State: CO Zip: 80202-				
<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>				
<b>Contact Information:</b>				

Contact Name	Phone	Email	Comment
Inspections, All		cogcc.inspections@encana.com	
		julia.carter@encana.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
356	WELL	PA	11/14/2012	GW	045-15494	N.PARACHUTE EF 11D-20 C29 5	RI
368	WELL	PA	11/14/2012	GW	045-15489	N. PARACHUTE EF07A-20 C29 59	RI
294648	WELL	DA	08/27/2014	GW	045-15547	N. PARACHUTE EF05A-20 C29 59	RI
294649	WELL	AL	07/08/2011	LO	045-15549	N.PARACHUTE EFH329-10S C29	RI
294650	WELL	AL	07/08/2011	LO	045-15548	N.PARACHUTE EFH329-6S C29 5	RI
294651	WELL	PA	08/27/2014	GW	045-15550	N. PARACHUTE EF06D-20 C29 59	RI
294652	WELL	PA	11/14/2012	GW	045-15551	N. PARACHUTE EF12C-20 C29 59	RI
294654	WELL	PA	11/14/2012	GW	045-15553	N. PARACHUTE EF12A-20 C29595	RI
294655	WELL	AL	07/08/2011	LO	045-15554	N. PARACHUTE EFH329-1S C29 5	RI
294656	WELL	AL	07/08/2011	LO	045-15555	N.PARACHUTE EFH320-1N C29 5	RI
294657	WELL	DA	08/27/2014	GW	045-15556	N. PARACHUTE EF05B-20 C29 59	RI
294659	WELL	DA	08/27/2014	GW	045-15558	N. PARACHUTE EF05C-20 C29 59	RI
294788	WELL	AL	07/08/2011	LO	045-15594	N. Parachute EF08D-19 C29 59	RI
294789	WELL	AL	07/08/2011	LO	045-15595	N. Parachute EF16B-19 C29 59	RI

294791	WELL	PA	08/27/2014	GW	045-15597	N. PARACHUTE EF12D-20 C29 59	RI
294792	WELL	AL	07/08/2011	LO	045-15598	N. Parachute EF13D-20 C29 59	RI
294793	WELL	AL	07/08/2011	LO	045-15599	N. Parachute EF13C-20 C29 59	RI
294794	WELL	AL	07/08/2011	LO	045-15600	N. Parachute EF13B-20 C29 59	RI
294795	WELL	PA	08/27/2014	GW	045-15601	N. PARACHUTE EF08C-19 C29 59	RI
294796	WELL	AL	07/08/2011	LO	045-15596	N. Parachute EF13A-20 C29 59	RI
294871	WELL	AL	07/08/2011	LO	045-15619	N. Parachute EF09C-19 C29 59	RI
294872	WELL	AL	07/08/2011	LO	045-15621	N. Parachute EF09D-19 C29 59	RI
294873	WELL	AL	07/08/2011	LO	045-15622	N. Parachute EF09A-19 C29 59	RI
294882	WELL	AL	07/08/2011	LO	045-15620	N. Parachute EF09B-19 C29 59	RI

**General Comment:**

This is a Final Reclamation and Abandoned Location Inspection for Twenty-Four PA & AL Wells listed in Inspected Facilities above. These Wells are on Location with Eight Producing Wells; therefore, these would be Well Releases on an Active Location.

Inspected Facilities				
Facility ID: <u>356</u>	Type: <u>WELL</u>	API Number: <u>045-15494</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
Facility ID: <u>368</u>	Type: <u>WELL</u>	API Number: <u>045-15489</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294648</u>	Type: <u>WELL</u>	API Number: <u>045-15547</u>	Status: <u>DA</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294649</u>	Type: <u>WELL</u>	API Number: <u>045-15549</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294650</u>	Type: <u>WELL</u>	API Number: <u>045-15548</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294651</u>	Type: <u>WELL</u>	API Number: <u>045-15550</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294652</u>	Type: <u>WELL</u>	API Number: <u>045-15551</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294654</u>	Type: <u>WELL</u>	API Number: <u>045-15553</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294655</u>	Type: <u>WELL</u>	API Number: <u>045-15554</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294656</u>	Type: <u>WELL</u>	API Number: <u>045-15555</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294657</u>	Type: <u>WELL</u>	API Number: <u>045-15556</u>	Status: <u>DA</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294659</u>	Type: <u>WELL</u>	API Number: <u>045-15558</u>	Status: <u>DA</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294788</u>	Type: <u>WELL</u>	API Number: <u>045-15594</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294789</u>	Type: <u>WELL</u>	API Number: <u>045-15595</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294791</u>	Type: <u>WELL</u>	API Number: <u>045-15597</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294792</u>	Type: <u>WELL</u>	API Number: <u>045-15598</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294793</u>	Type: <u>WELL</u>	API Number: <u>045-15599</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294794</u>	Type: <u>WELL</u>	API Number: <u>045-15600</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>294795</u>	Type: <u>WELL</u>	API Number: <u>045-15601</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>

Inspector Name: Colby, Lou

Facility ID:	294796	Type:	WELL	API Number:	045-15596	Status:	AL	Insp. Status:	RI
Facility ID:	294871	Type:	WELL	API Number:	045-15619	Status:	AL	Insp. Status:	RI
Facility ID:	294872	Type:	WELL	API Number:	045-15621	Status:	AL	Insp. Status:	RI
Facility ID:	294873	Type:	WELL	API Number:	045-15622	Status:	AL	Insp. Status:	RI
Facility ID:	294882	Type:	WELL	API Number:	045-15620	Status:	AL	Insp. Status:	RI

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: All these PA & AL Wells are being Failed for Final Reclamation. Though it appears that Documentation is in place; there is evidence of Wells remaining on Site. Remnants of Cellars and Concrete slabs are visible through gravel layer. It is impossible to tell if Conductors or Well casings (improperly Plugged) are buried in Cellars and which Cellar corresponds with which Well.

Inspector Name: Colby, Lou

Corrective Action:	<b>Remove all evidence of PA &amp; AL Wells.</b>	Date	<b>06/01/2020</b>
Overall Final Reclamation	<b>Fail</b>	Well Release on Active Location	<input checked="" type="checkbox"/>
		Multi-Well Location	<input checked="" type="checkbox"/>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692401516	Inspection photos RI	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4969740">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4969740</a>