

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2019

Submitted Date:

10/16/2019

Document Number:

688306005**FIELD INSPECTION FORM**Loc ID 322194 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Grimes, Meghan		mgrimes@petrosharecorp.com	
Brown, Devin		dbrown@petrosharecorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209648	WELL	SI	06/01/2018	OW	039-06553	NORDMAN TRUST 41-20	TA

General Comment:[MIT Inspection, passed](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	OTHER	
Comment:	Stained soil at engine inside shed, non E&P waste.	
Corrective Action:	Remove and properly dispose of stained soil at engine.	Date: 11/15/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:		
Yes/No		
Comment:		
Corrective Action:	Date:	

Flaring:		
Type		
Comment:		
Corrective Action:	Date:	

Inspected FacilitiesFacility ID: 209648 Type: WELL API Number: 039-06553 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA because tank battery is decommissioned.

MIT Form 21 is attached.

0 psi on casing

0 min 500 psi

5 min 500 psi

10 min 500 psi

15 min 500 psi

0 psi on casing

Corrective Action: _____ Date: _____

BradenHeadComment: -10 psi, took 50 secs to suck down

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402211759	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964609
688306009	Petroshare Nordman Trust 41-20 Rig 15 sign at CR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964598
688306010	Petroshare Nordman Trust 41-20 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964599
688306011	Petroshare Nordman Trust 41-20 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964600
688306012	Petroshare Nordman Trust 41-20 Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964601