

Inspection Photos
Operator: BP America
Location/API #: 067-06717
Date: 10-16-2019



Photo 1. View of the project area from the northern well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is well established, and comprised largely with perennial grasses such as western wheatgrass and shrubs such as rubber rabbitbrush.



Photo 3. View of vegetation growing around wellhead, needing management.



Photo 4. View of musk thistles within the project area.



Photo 5. View of reference area vegetation north of the project area. Vegetation is comprised of sagebrush and mixed perennial grasses such as smooth brome, western wheatgrass, and sand dropseed.