

Inspection Photos
Location Name: MANVILLE 42-14
API#: 05-071-08385
INSP. #: 695101577



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos

Location Name: MANVILLE 42-14

API#: 05-071-08385

INSP. #: 695101577



PHOTO 3: 3 UNMARKED UNUSED RISERS, ONE 1" AND TWO 2" RISERS NEAR ORIGINAL WELLHEAD. REMOVE RISER COMPLY WITH NTO. CA DATE 11-18-19

PHOTO 4: IT HARD TO SEE IN PHOTO BUT THERE IS AN AREA OF IMPACTED SOIL NEAR FULL GAS DRAIN ON COMPRESSOR. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-18-19