

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-08862**  
**Date: 10-16-2019**



Photo 1. View of the project area from the northern well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is well established, and comprised largely with perennial grasses such as western wheatgrass and shrubs such as rubber rabbitbrush.



Photo 3. View of vegetation growing around wellhead, needing management. Noxious musk thistles are scattered within these weedy areas.



Photo 5. View of reference area vegetation north of the project area. Vegetation is comprised of sagebrush and mixed perennial grasses such as smooth brome, western wheatgrass, and sand dropseed.