

Inspection Photos
Operator: BP America
Location/API #: 067-07817
Date: 10-16-2019



Photo 1. View of the project area from the southeastern project area facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is well established, and comprised largely with perennial grasses such as western wheatgrass and smooth brome.



Photo 3. View of Canada thistle within the western portion of the project area.



Photo 4. View of vegetation growing around wellhead, needing management.



Photo 5. View of reference area vegetation comprised of sagebrush, rubber rabbitbrush, and perennial grasses and forbs representative of the vegetation type.