

Inspection Photos
Location Name: Sam Funakoshi A. #1 & #2 TB
Location ID: 318417



Photo #1 TB sign

Photo #2 TB

Inspection Photos
Location Name: Sam Funakoshi A. #1 & #2 TB
Location ID: 318417



Photo #3 Dead weeds along TB berm



Photo #4 Dead weeds by Heated Horiz. Sep.

Inspection Photos
Location Name: Sam Funakoshi A. #1 & #2 TB
Location ID: 318417



Photo #5 Production lines