

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2019

Submitted Date:

10/17/2019

Document Number:

689501004**FIELD INSPECTION FORM**Loc ID 319611 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445284	SPILL OR RELEASE	CL	03/29/2017		-	Haas 1	EI

General Comment:[COGCC Environmental Inspection of Remediation Project #10100](#)

Inspected Facilities									
Facility ID:	445284	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

--

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: [COGCC inspection of remediation project #10100. Monitoring wells are present and appear in good condition. Additional monitoring wells have been added since last Form 27 submittal.](#)

Corrective Action: [Submit a Supplemental Form 27 with an updated groundwater monitoring program on the Remediation Action Plan tab, a map showing monitoring well locations, boring logs from recent monitoring well installation, and any analytical data collected since last Form 27 submittal.](#)

Date: 11/09/2019

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
Contact area EPS Nikki Graber with any questions regarding Form 27 Submittal.	oakmank	10/17/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402213550	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966169
689501005	Monitoring well photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966129