

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/09/2019

Submitted Date:

10/17/2019

Document Number:

689501012

**FIELD INSPECTION FORM**
 Loc ID 322581 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10311

Name of Operator: SRC ENERGY INC

Address: 1675 BROADWAY SUITE 2600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@srcenergy.com	ALL INSPECTIONS
Graber, Nikki		nikki.graber@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243887	WELL	PR	09/01/2018	OW	123-11679	KINDSFATER #23-13	EI

**General Comment:**

COGCC Environmental Inspection to determine the status of pit facility ID 111031. Pit location was determined based on aerial imagery. Stunted vegetation was present at the historic pit location. Operator is instructed to submit a Form 27 for site characterization of the historic pit area.

Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site condition at the time of inspection.



**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Pit location was determined based on aerial imagery (photos 7-11). Stunted vegetation was present at the historic pit location (photos 5&6).

Corrective Action: Operator shall submit a Form 27 Site Investigation and Remediation Workplan for site characterization of the historic pit area.

Date: 11/09/2019

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Contact area EPS Nikki Graber with any questions regarding Form 27 Submittal.	oakmank	10/17/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402213556	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966172">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966172</a>
689501013	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966133">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966133</a>