

Inspection Photos

API: 05-071-06130

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 10/24/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06130 | Date: 10/24/2019

Inspection Photos



Photo 1. The culvert has been cleaned out of sediment. Straw blanket was installed in the disturbance area.

Lat/Long:37.09153/-104.93557



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 10/24/2019

Inspection Photos



Photo 2. Well sign installed at metal shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 10/24/2019

Inspection Photos



Photo 3. There is oil spilled into the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 10/24/2019