

**Inspection Photos**  
**Location Name:** VEGA USX /A03-05  
**Location #:** 422947



Colorado Oil & Gas Conservation Commission  
40.51701, -104.5427, 1452.0m, 174°  
09/12/2019 01:53:41 PM

**Photo #1**  
**Vega USX A03-05** (05-123-33459) Wellsite  
**Shut-In | SI**  
**Weeds**  
*prior insp.*



Colorado Oil & Gas Conservation Commission  
40.51697, -104.54268, 1452.0m, 191°  
10/24/2019 01:11:13 PM

**Photo #2**  
**Vega USX A03-05** Wellsite  
**Shut-In | SI**  
**Weeds NOW appear mitigated**

**Inspection Photos**  
**Location Name:** VEGA USX /A03-05  
**Location #:** 422947



**Photo #3**  
**Vega USX A03-05 Battery**  
**Shut-down | Inactive**  
**Weeds**  
*prior insp.*



**Photo #4**  
**Vega USX A03-05 Battery**  
**Shut-down | Inactive**  
**Weeds NOW appear mitigated**



**Inspection Photos**  
**Location Name:** VEGA USX /A03-05  
**Location #:** 422947



**Photo #5**  
**Vega USX A03-05** Separator | ECD areas  
**Shut-down | Inactive**  
**Weeds**  
*prior insp.*



**Photo #6**  
**Vega USX A03-05** Separator | ECD areas  
**Shut-down | Inactive**  
**Weeds NOW appear mitigated**