

**Inspection Photos**  
**Location Name: Kummer PC LE 23-99HZ**  
**Location ID: 421018**



**Photo 1 – Tank Battery**



**Photo 2 – Pumping Unit**

**Inspection Photos**  
**Location Name: Kummer PC LE 23-99HZ**  
**Location ID: 421018**



**Photo 3 – Tank missing Content and Capacity**



**Photo 4 – Unused Containment**