

**Inspection Photos**  
**Location Name: Weld Weitzel 5-33**  
**Location ID: 327432**



**Photo 1 – Pumping Units, weeds**



**Photo 2 – Weeds at Heater Treater**

**Inspection Photos**  
**Location Name: Weld Weitzel 5-33**  
**Location ID: 327432**



**Photo 3 – Weeds at Crude Oil Tanks. Tanks are rusted, paint is peeling**



**Photo 4 – NFPA Label has faded, no longer visible**

**Inspection Photos**  
**Location Name: Weld Weitzel 5-33**  
**Location ID: 327432**



**Photo 5 – NFPA Label has faded, no longer visible**



**Photo 6 – Weeds at Water Tank**