

Inspection Photos

API#077-08101

Operator: Caerus

Inspection Number: 692401522

Inspection Date: 10/15/19





Photo#1:
Views of reclaimed portion of Location.

October 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Thomas API#077-08101



Photo#2:
View of pad area to remain un-reclaimed.



Photo#3:
View of pad area to remain un-reclaimed.

October 16, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Thomas API#077-08101



Photo#4:
View of upper portion of access road where water is compromising road stability.

October 16, 2019



Photo#5:
View of upper portion of access road where water is compromising road stability.