

Inspection Photos
Operator: BP America
Location/API #: 067-10003
Date: 10-16-2019



Photo 1. View of the project area from the northeastern project area facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of the eastern fill slope, from the southeastern edge facing northward. Tall annual weeds (kochia and mustard) are threatening desirable species establishment and need to be managed.



Photo 4. Birdseye view of desirable species becoming established beneath dense annual vegetation. Desirable cover is approximately 20 percent.



Photo 5. View of weeds growing around equipment, needing to be controlled.



Photo 6. View of reference area vegetation north of the project area, comprised of sagebrush and pinyon-juniper woodland, interspersed with native and non-native grasses and forbs.