

Inspection Photos
Operator: BP America
Location/API #: 067-09009
Date: 10-16-2019



Photo 1. View of the project area from the northeastern corner facing center. Stakes in mid-ground indicate open permits for two wells on the location.



Photo 2. View of erosional channel and bare soils within the well pad cut-slope.



Photo 3. View of the western fill slope from the northwestern project area facing southward. Revegetation is progressing here, largely with grasses such as western wheatgrass and smooth brome.



Photo 4. View of reference area comprised of mixed pinyon juniper woodland and gambel oak shrubland.