

Inspection Photos
Operator: BP America
Location/API #: 067-09641
Date: 10-22-2019



Photo 1. View of the project area from the southwestern corner facing center. Well pad remains in place.



Photo 2. View of the western fill slope from the southwestern edge facing northward.



Photo 3. View of the eastern project area from the southeastern corner facing northward. Soil piles remain in the eastern project area.



Photo 4. View of the northern project area from the northeastern corner facing westward.



Photo 5. View of reference area vegetation comprised of sagebrush shrubland, interspersed with mixed native and non-native grasses and forbs.