

Inspection Photos
Location Name: Triangle 22 Pad
Location ID: 432327



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Triangle 22 Pad
Location ID: 432327



Photo 3: Wellhead Sign



Photo 4: Wellhead

Inspection Photos
Location Name: Triangle 22 Pad
Location ID: 432327




Photo 5: Wellhead Sign



Photo 6: Wellhead



Inspection Photos
Location Name: Triangle 22 Pad
Location ID: 432327



Photo 7: Wellhead Sign



Photo 8: Wellhead

Inspection Photos
Location Name: Triangle 22 Pad
Location ID: 432327



Colorado Oil and Gas Conservation Commission
40.56218, -104.64986, 1457.7m, 178°
Oct 28, 2019 14:58:55

Photo 9: Tank Battery Sign



Colorado Oil and Gas Conservation Commission
40.56221, -104.65001, 1456.1m, 125°
Oct 28, 2019 14:59:49

Photo 10: Tank Battery

Inspection Photos
Location Name: Triangle 22 Pad
Location ID: 432327



Photo 11: Unused Riser



Photo 12: Unused Riser

