

Inspection Photos

API#045-06682

Operator: Chevron

Inspection Number: 692401532

Inspection Date: 10/25/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

October 25, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Shale PA API#045-06682



Photo#2:
View up Access Road from entry.



Photo#3:
View of Access Road towards entry.

October 25, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Shale PA API#045-06682



Photo#4:
Spotty, bare and weedy (ruderal/Debris weeds)
in areas.



Photo#5:
Spotty, bare and weedy (ruderal/Debris weeds)
in areas..

October 25, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Shale PA API#045-06682