

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/25/2019

Submitted Date:

10/25/2019

Document Number:

697000124

FIELD INSPECTION FORM

Loc ID 414254 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414257	WELL	PR	06/03/2010	GW	125-11719	ZUEGE 33-35	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Lease sign by county road		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead, VGS and meter run		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried by meter run		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	414257	Type:	WELL	API Number:	125-11719	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT