

Inspection Photos

Loc#335936

Operator: Terra

Inspection Number: 692401543

Inspection Date: 10/25/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Views of Location Interim Rec areas.

October 25, 2019




Photo#2:
Stormwater discharge hole developed on NE side of Well corral Panels.

October 25, 2019



Photo#3:
Ditches on either side of Access road need maintenance

October 25, 2019



Photo#4:
Ditches on either side of Access road need maintenance.