



00255097

PIT INSPECTION FORM

DATE 11/19/86 OPERATOR Romac FIELD Cayuse
COUNTY Logan LEASE Houston 20-1 LOCATION SWSW20-9N-52W

CLASS 3 - C LEASE SIGN: YES ☒ NO TANK ID: YES ☒ NO

TYPE OF OBSERVED WATER DISPOSAL:

☒ EVAP. PITS ☐ TANKS/TRUCKED ☐ INJECTED* ☐ NOT DETERMINED ☐ NA

ESTIMATED WATER PRODUCTION GPM * (34.3) = BPD

SKIM TANK: SIZE none GALS, ☐ METAL ☐ FIBERGLASS ☐ PLASTIC ☐ CEMENT
COVERED ☐ YES ☐ NO, OVERFLOW ☐ YES ☐ NO

PITS:

SKIM PIT(S)

EVAPORATIVE PIT(S)

SIZE: none * = SQFT

50 * 50 = SQFT

MATERIAL Native soil

* = SQFT

SCREEN: YES NO

* = SQFT

SCREEN COLLAPSED YES NO

TOTAL = SQFT

FLAGS YES NO

LINER MATERIAL: COMM. BENT.

OIL COVERED %

SYNTHETIC

NATIVE SOIL

NONE

OIL COVERED %

BREACHED YES NO

COMMENTS

Well shut in, pit dry, no surface
equipment at well - Removed

* Compressor Station in NWNW 29

PIT PERMIT YES NO, LINER REQUIRED YES NO, TDS ppm

REPORTED WATER PRODUCTION BBL/DAY LEASE NUMBER

* INJECTION FACILITY: NAME LOCATION

NOTICE SENT YES NO DATE SENT INSPECTOR S. Pott