

Inspection Photos
Location Name: North Platte /32-34
Location #: 413457



Photo #1

North Platte 31-34 (05-123-30597) Wellsite

Shut-In| SI

.Sign with company & well name NOT posted



Photo #2

North Platte 32-34 (05-123-33613) Wellsite

Shut-In| SI

Inspection Photos
Location Name: North Platte /32-34
Location #: 413457



Photo #3

North Platte 31-34, 32-34, 41-34, 42-34 Battery

Shut-down | Inactive