

Pit Status Evaluation Form

Pit Overview:

Pit Name: HOSMER VETTER	Facility ID: 118895
Current Status: Unknown	Status Date:
Current Operator: MGF OIL CORPORATION / 51933	
Updated Operator:	
Form 15 Pit Permit Doc #: NA	Permit Date: NA
Related Facilities: Facility ID 463387 (TB), API # 05-001-07950 (Facility ID 202545) API # 05-001-07301 (Facility ID 201897), API # 05-001-07267 (Facility ID 201863)	

County: ADAMS			
Township: 1S	Range: 64W	Section: 32	QQ:
Original Latitude/ Longitude:		/	
Updated Latitude/ Longitude: 39.918829		/ -104.583171	
Basis for Location Change:			
Lat/Long created at tank battery (aerial imagery)			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---------------------------------------------|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 697863 | Date: 6/18/1984 |
| | Doc #: 697865 | Date: 5/2/1990 |
| | Doc #: 304277 | Date: 6/26/1998 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2542803 | Date: 12/26/1995 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location. Pit inventory report and inspection reports document a concrete water vault on location. Pit status has been changed to Closed.