

Inspection Photos

API#077-08567

Operator: Caerus

Inspection Number: 692401548

Inspection Date: 10/16/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View North over Location.



Photo#2:
View South over Location.

October 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Shear API#077-08567



Photo#3:
View East over Location.

Photo#4:
View West over Location.

October 16, 2019



Photo#5:
Close up of heavy Cheatgrass growth on site.

October 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Shear API#077-08567



Photo#6:
View of Reference area to West of Site.

October 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Shear API#077-08567