

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2019

Submitted Date:

10/30/2019

Document Number:

688306232**FIELD INSPECTION FORM**Loc ID 420585 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96340Name of Operator: WIEPKING-FULLERTON ENERGY LLCAddress: 106 GLENMOOR LNCity: ENGLEWOOD State: CO Zip: 80113**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shalberg, Greg	(719) 688-3547	gregshalberg@aol.com	
Halde, Kerry	(719) 340-0329	haldeoil@hotmail.com	<a href="#">All Inspections</a>
Boone, Linda	(720) 271-8605	LDBoonePar@aol.com	<a href="#">All Inspections</a>
Herian, Tim	(316) 655-9200	therian1@cox.net	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420578	WELL	IJ	06/06/2013	DSPW	073-06440	Napali 1	AC

**General Comment:**[Inspection north tank \(see attached photo\). Check mechanical conditions.](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

OTHER

Comment: Check valve on east side on north fiberglass tank (see attached photo).

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 11/18/2019

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

**Inspected Facilities**Facility ID: 420578 Type: WELL API Number: 073-06440 Status: IJ Insp. Status: AC**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306233	Wiepking-Fullerton Energy LLC, Napali 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978128">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978128</a>
688306234	Wiepking-Fullerton Energy LLC, Napali 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978129">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978129</a>
688306235	Wiepking-Fullerton Energy LLC, Napali 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978130">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978130</a>