

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2019

Submitted Date:

10/31/2019

Document Number:

696101492

**FIELD INSPECTION FORM**
 Loc ID 413457 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412513	WELL	SI	04/01/2019	OW	123-30597	NORTH PLATTE 31-34	SI
423532	WELL	SI	04/01/2019	GW	123-33613	North Platte 32-34	SI

**General Comment:**

This is a WELL &amp; BATTERY inspection.

Well(s): 2 ; Shut-In | SI.

Battery: Shut-down | Inactive

Centralized Battery serves 2 Location IDs (413457, 413974).

(Well(s): 4 ; 2: Shut-In | SI ; 2: Temporarily Abandoned | TA).

(1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign with company & well name NOT posted at North Platte 31-34 wellsite. Refer to Rule 210.b. (60 Days). * Post sign with company & well name at North Platte 31-34 wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/30/2019. See photo #1.			
Corrective Action:	* Post sign with company & well name at North Platte 31-34 wellsite. Comply w/ Rule 210.b. See photo #1.			Date: 12/30/2019
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	2 - Wellsites: Iron panel			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Surroinded by earth berms.			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Gas Meter Run	# 1			
Comment:				

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	2 - Wellsites: Appears plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	2 - Wellsites		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:	Controls crude oil tank VOCs. Pilots: OFF   Shut-down		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 2 Location IDs (413457, 413974).				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:			Date:		

**Paint**

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ crude oil tanks.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		40.363892,-104.413841

Comment: [Equalizer lines connect crude oil tanks.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ produced H2O vault.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	
Date:	

**Inspected Facilities**Facility ID: 412513 Type: WELL API Number: 123-30597 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Shut-In | SI. Observed production valves closed.  
COGCC records indicate last production: 03/2019.Corrective Action:  Date: Facility ID: 423532 Type: WELL API Number: 123-33613 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Shut-In | SI. Observed production valves closed.  
COGCC records indicate last production: 03/2019.Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 10/30/2019 at approximately 16:32 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: North Platte /32-34  Location ID: 413457  Well Names: North Platte 31-34, North Platte 32-34  API: 05-123-30597, 05-123-33613  Location County: Weld County, Colorado  Weather: Clear w/ prior snow cover</p> <p>While there, I observed:  Well(s): 2 ; Shut-In   SI.  Battery: Shut-down   Inactive</p> <p>Centralized Battery serves 2 Location IDs (413457, 413974).  (Well(s): 4 ; 2: Shut-In   SI ; 2: Temporarily Abandoned   TA).  (1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)</p> <p>During this inspection, the following possible compliance issues were observed:  1.) Sign with company &amp; well name NOT posted at North Platte 31-34 wellsite.  Refer to Rule 210.b. (60 Days).  * Post sign with company &amp; well name at North Platte 31-34 wellsite.  Comply w/ Rule 210.b.  Corrective Action date: 12/30/2019.  See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/31/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402227996	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977876">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977876</a>
402229215	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978714">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978714</a>

696101493	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977875">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977875</a>
-----------	-------------	---

