

Inspection Photos

Location Name: North Platte 44-11-28HZ /Facility

Location #: 331805



Photo #1

DOW 41-33 (05-123-21329) Wellsite

Plugged & Abandoned | PA

Improper Abandonment of flowline | NOT LOTO
prior insp.



Photo #2

DOW 41-33 Wellsite

Plugged & Abandoned | PA

Proper Abandonment of flowline
NOW marked & LOTO
(Operator provided photo)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: North Platte 44-11-28HZ /Facility

Location #: 331805



Photo #3

DOW 41-33 Separator

Plugged & Abandoned | PA
Proper Abandonment of flowline
NOW marked & LOTO
(Operator provided photo)



Photo #4

North Platte 44-11-28HZ Battery

Shut-down | Inactive
DOW 41-33 well formerly connected to Battery
prior insp.