

Inspection Photos

API#057-06510

Operator: Dakota Exploration

Inspection Number: 692401157

Inspection Date: 6/28/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of location to West. Insert is of reference area vegetation surrounding Location.

June 28, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Dakota Exploration State API#057-06510



Photo#2:
View along back side of Tanks to Northwest.



Photo#3:
Canada thistle established on north berm.

June 28, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Dakota Exploration State API#057-06510



Photo#4:
Canada thistle established on Pad area.

June 28, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Dakota Exploration State API#057-06510



Photo#5:

Concrete pump jack base to west of wellhead and metal container adjacent to it remain on location.

June 28, 2019



Photo#6:



Photo#7:
Rat Hole is open adjacent to Wellhead and full, with no freeboard of assumed stormwater.



Photo#8:

June 28, 2019