

Inspection Photos
Operator: BP America
Location/API #: 067-08833
Date: 10-24-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with shrubs and grasses such as rubber rabbitbrush, western wheatgrass, and smooth brome.



Photo 3. View of erosional tunnel approximately 3.5 feet in diameter within the eastern project area.



Photo 4. View of reference are vegetation comprised of mixed pinyon juniper woodland, and sagebrush shrubland with native grasses such as James galleta and forbs such as perky Sue.