

Inspection Photos

Location Name: TOP GEAR 14-21 FOLLOWUP

API#: 05-071-07602

INSP. #: 695101654



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos

Location Name: TOP GEAR 14-21 FOLLOWUP

API#: 05-071-07602

INSP. #: 695101654



Colorado Oil & Gas Conservation Commission
37.06354, -104.68242, 2174.0m, 78°
2019/11/04 11:36:06



Colorado Oil & Gas Conservation Commission
37.06373, -104.68234, 2182.0m, 161°
2019/11/04 11:36:54

PHOTO 3: FLUID IN EARTH PIT IS ABOVE FREEBOARD MARKER. Lower fluid level so at least two feet of freeboard exists per Rule 902.b. CA DATE 11-5-19 (THIS IS THE SECOND WORKING OF FLUID LEVEL IN PIT ABOVE 2' FREEBOARD PIT SIZE AND DEPTH MAY BE A FACTOR IN THIS REOCCURRENCE, AT TIME OF NEXT REINSPECTION IF FLUID LEVEL IN PIT IS OUT OF COMPLIANCE ENFORCEMENT MAY BE CONSIDERED).

PHOTO 4: UNUSED EQUIPMENT (WELLHEAD HOUSE IS PLACED TO THE SIDE OF LOCATION AND IS NOT IN USE). REMOVE OR USE UNUSED EQUIPMENT IN ACCORDANCE WITH RULE 603.f. CA DATE 12-4-19

Inspection Photos

Location Name: TOP GEAR 14-21 FOLLOWUP

API#: 05-071-07602

INSP. #: 695101654



**PHOTO 5: TRASH IN SEVERAL SPOT AROUND
LOCATIO. POLICE LOCATION AND SURROUNDING
AREA FOR TASH AND INSPECT AT REGULAR
INTERVALS TO PREVENT TRASH ON AROUND
LOCATION IN ACCORDANCE WITH RULE 603.f. CA
DATE 12-4-19**

PHOTO 6: MORE TRASH ON LOCATION



Inspection Photos

Location Name: TOP GEAR 14-21 FOLLOWUP

API#: 05-071-07602

INSP. #: 695101654



**PHOTO 5: TRASH IN SEVERAL SPOT AROUND
LOCATIO. POLICE LOCATION AND SURROUNDING
AREA FOR TASH AND INSPECT AT REGULAR
INTERVALS TO PREVENT TRASH ON AROUND
LOCATION IN ACCORDANCE WITH RULE 603.f. CA
DATE 12-4-19**

PHOTO 6: MORE TRASH ON LOCATION

