

Inspection Photos
Location Name: Ocoma 31-17
API ID: 123-15026



Photo# 1 Wellhead, Sign & Weeds on 9/26/19

Photo# 2 Wellhead, Sign & Weeds on 11/5/19

Inspection Photos
Location Name: Ocoma 31-17
API ID: 123-15026



Photo #3 Weeds grown around Wellhead on 9/26/19

Photo #4 Weeds grown around Wellhead on 11/5/19