

Location Name: Grayhorse Energy Operating – Writebol Spill ID 468817
Inspection Date: 10/21/2019



Photo # 1 – Spill cleanup in progress at the tank battery



Location Name: Grayhorse Energy Operating – Writebol Spill ID 468817
Inspection Date: 10/21/2019



Photo # 2 – Spill cleanup in progress at the tank battery

Location Name: Grayhorse Energy Operating – Writebol Spill ID 468817
Inspection Date: 10/21/2019



Photo # 3 – Spill cleanup in progress at the tank battery



Location Name: Grayhorse Energy Operating – Writebol Spill ID 468817
Inspection Date: 10/21/2019



Photo # 4 – Spill cleanup in progress at the tank battery

Location Name: Grayhorse Energy Operating – Writebol Spill ID 468817
Inspection Date: 10/21/2019



Photo # 5 – Impacted soil stockpile at the tank battery

