

Inspection Photos
Location Name: Greasewood 04-8H
Location ID: 430817



Photo 1 – Tank Battery




Photo 2 – Wellhead



Inspection Photos
Location Name: Greasewood 04-8H
Location ID: 430817



Photo 3 – Glycol Day barrel containment is missing Wildlife netting