

Inspection Photos
Location Name: Milton H Nelson B #1
Location ID: 336292



Photo #1 WH sign



Photo #2 unused cement slabs



Inspection Photos
Location Name: Milton H Nelson B #1
Location ID: 336292




Photo #3 unused electric panels, fence poles and cement slabs