

Inspection Photos
Location Name: Colclosure #42-21
Location ID: 305962



Photo #1 WH sign



Photo #2 PU

Inspection Photos
Location Name: Colclosure #42-21
Location ID: 305962



Photo #3 WH



Photo #4 WH

Inspection Photos
Location Name: Colclosure #42-21
Location ID: 305962



Photo #5 PU missing prime mover



Photo #6 PU belt cover