

Inspection Photos
Location Name: Rickards 41-10H
Location ID: 418936



Photo 1 – Pumping Unit



Photo 2 – Tank Battery



Inspection Photos
Location Name: Rickards 41-10H
Location ID: 418936



Photo 3 – Sign does not reflect current Operator



Photo 4 – Sign does not reflect current Operator



Inspection Photos
Location Name: Rickards 41-10H
Location ID: 418936



Photo 5 – Unmarked 2” Risers on the East side of the Treater House



Photo 6– South Middle Tank Content and Capacity label is faded no longer legible

Inspection Photos
Location Name: Rickards 41-10H
Location ID: 418936




Photo 7 – South East Tank Content and Capacity label is faded no longer legible. NFPA Label also needs replaced.



Photo 8 – Sign out by the lease road entrance

