

## Pit Status Evaluation Form

## Pit Overview:

<b>Pit Name:</b> STEVENS 34-15	<b>Facility ID:</b> 114252
<b>Current Status:</b> Unknown	<b>Status Date:</b>
<b>Current Operator:</b> PETROSHARE CORPORATION / 10454	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b>	<b>Permit Date:</b>
<b>Related Facilities:</b> API # 05-001-08741	

<b>County:</b> ADAMS			
<b>Township:</b> 1S	<b>Range:</b> 65W	<b>Section:</b> 15	<b>QQ:</b> CSE
<b>Original Latitude/ Longitude:</b> 39.96115 / -104.645474			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

**Pit Inspection/Information Request:**

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #:                 | Date:            |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 1389202        | Date: 4/29/1986  |
|                                     | Doc #: 698050                               | Date: 11/9/1989  |
|                                     | Doc #: 894232                               | Date: 11/30/1999 |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:            |
| <input checked="" type="checkbox"/> | Form 4 Sundry Notice – Doc #: 234776        | Date: 2/22/1989  |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:            |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223543              | Date: 3/27/1998  |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                  |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/>            | Other:                                      |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

No evidence of a pit on location

#### Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location. Pit inventory report and inspection reports document a fiberglass tank on location. Pit status has been changed to Closed.