

Inspection Photos

API: 05-071-07546

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/5/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 11/5/2019

Inspection Photos



Photo 1. There is an area of erosion along the main road at Lat/Long:37.14023,-104.81186.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 11/5/2019

Inspection Photos



Photo 2. There is an area of erosion along the cut slope of the access road at Lat/Long:37.14248,-104.81373.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 11/5/2019

Inspection Photos



Photo 3. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 11/5/2019

Inspection Photos



Photo 4. There were a few bull thistle plants found at the location. Seed heads should be removed if still present.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 11/5/2019

Inspection Photos



Photo 5. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 11/5/2019