

## Inspection Photos Location #335534



location



location





## Inspection Photos Location #335534



**Liner patch not holding**



**Holes in liner**





## Inspection Photos Location #335534



**Fluid in drip pan next to lit burner**



**Damaged containment**





## Inspection Photos Location #335534



**Stain in front of battery**



**Stain in front of battery same area as damaged battery**





## Inspection Photos Location #335534



**Needs slope stabilization (west side of pad)**



**Needs slope stabilization (south side of pad)**





## Inspection Photos Location #335534



Weeds behind south tank battery next to electric box



Containers in containment

