

Inspection Photos
Location Name: Jack A. Mleynek #1
Location ID: 318147



Photo #1 WH sign faded emergency contact number not legible.

Photo #2 WH sign/PU

Inspection Photos
Location Name: Jack A. Mleynek #1
Location ID: 318147



Photo #3 WH with dead weeds/debris around it.

Photo #4 Dead weeds/debris around PU.

Inspection Photos
Location Name: Jack A. Mleynek #1
Location ID: 318147



Photo #5 Electric panel with dead weeds/debris around it.

Photo #6 Dead weeds/debris around PU.

Inspection Photos
Location Name: Jack A. Mleynek #1
Location ID: 318147



Photo #7 PU fence missing pole causing it to lean.