

Inspection Photos

Location Name: UPRR 43 Pan Am h 6

Location ID: 318050



Pic 1 rods not connected to pumping unit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources