

Inspection Photos
Location Name: Hopkins 32-19 (1-67) 1
Location ID: 317960



Pic 1 stained soil/mechanical issues



Pic 2