

## WELL SITE INSPECTION FORM



WELL NAME Walters #1  
OPERATOR Intermountain Oil  
LOCATION SENE 11-9N-54W  
FIELD Cedar Creek

API NUMBER 05 - 075 - 9126  
PERMIT NUMBER \_\_\_\_\_  
COUNTY Logan  
INSPECTOR SP

## AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) \_\_\_\_\_ DATE 8/10/89 FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_

=====

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_  
CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_  
RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_  
DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_  
TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_  
SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls  
EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_  
METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

## AL/PA/DA INSPECTION

DATE PLUGGED: \_\_\_\_\_ DATE PERMIT EXPIRED: \_\_\_\_\_  
HOLE PLUGGED: YES ☒ NO \_\_\_\_\_ PITS BACKFILLED: YES ☒ NO \_\_\_\_\_  
MATERIAL BURIED: YES ☒ NO \_\_\_\_\_ NA \_\_\_\_\_ SITE CLEAN: YES ☒ NO \_\_\_\_\_  
BOND RELEASE OK: YES ☒ NO \_\_\_\_\_ FED \_\_\_\_\_ HOLE MARKER: YES \_\_\_\_\_ NO \_\_\_\_\_

DATE OF SAFETY/STATUS INSPECTION \_\_\_\_\_

COMMENTS - left message w/ Intermountain Oil to  
pull leadmen 8/11/89  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_