

Inspection Photos
Location Name: Deterding 31-02
API: 05-125-11793



Brian Welsh SE Field Inspector COGCC
40.01559, -102.33029, 3778.4ft
11/07/2019 10:45:12


1. Location



Brian Welsh SE Field Inspector COGCC
40.01569, -102.33024, 3771.2ft
11/07/2019 10:45:54

2. Access erosion near location

Inspection Photos
Location Name: Deterding 31-02
API: 05-125-11793



3. Erosion at BMPs that are washed out



4. Erosion on access looking at location