

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/08/2019

Submitted Date:

11/11/2019

Document Number:

698100086

FIELD INSPECTION FORM
 Loc ID 334436 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections
Heil, John		john.heil@state.co.us	
Bankert, Wayne		wbankert@laramie-energy.com	
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301474	WELL	PR	06/22/2017	OW	077-09984	Piceance 29-01E	EI
301478	WELL	PR	08/11/2017	OW	077-09988	Piceance 29-04M	EI
301481	WELL	PR	06/19/2017	OW	077-09989	Piceance Federal 29-01W	EI
301482	WELL	PR	06/20/2017	OW	077-09990	Piceance Federal 29-02W	EI
301483	WELL	PR	06/15/2017	OW	077-09991	Piceance Federal 29-03W	EI
301484	WELL	PR	10/23/2017	OW	077-09992	Piceance 29-05M	EI
301485	WELL	PR	08/11/2017	OW	077-09993	Piceance Federal 29-04W	EI
301486	WELL	PR	06/19/2017	OW	077-09994	Piceance 29-02E	EI
301487	WELL	PR	08/15/2017	OW	077-09995	Piceance Federal 29-05W	EI
301488	WELL	PR	09/07/2017	OW	077-09996	Piceance Federal 29-10W	EI
301489	WELL	PR	09/10/2017	OW	077-09997	Piceance Federal 29-11W	EI
301490	WELL	PR	08/13/2017	OW	077-09998	Piceance 29-07M	EI
301491	WELL	PR	08/15/2017	OW	077-09999	Piceance 29-06M	EI
301493	WELL	PR	09/04/2017	OW	077-10001	Piceance Federal 29-06W	EI
301494	WELL	PR	09/04/2017	OW	077-10002	Piceance Federal 29-08W	EI

301495	WELL	PR	09/11/2017	OW	077-10003	Piceance Federal 29-09W	EI
301496	WELL	PR	09/13/2017	OW	077-10004	Piceance Federal 29-07W	EI
301497	WELL	PR	06/17/2017	OW	077-10005	Piceance 29-03E	EI
448318	WELL	PR	07/02/2017	OW	077-10328	Piceance Federal 29-15W	EI
448319	WELL	PR	07/02/2017	GW	077-10329	Piceance Federal 29-13W	EI
448320	WELL	PR	07/02/2017	GW	077-10330	Piceance Federal 29-12W	EI
448321	WELL	PR	07/03/2017	GW	077-10331	Piceance Federal 29-16W	EI
448322	WELL	PR	07/01/2017	OW	077-10332	Piceance Federal 29-14W	EI
448323	WELL	PR	07/14/2017	GW	077-10333	Piceance Federal 29-17W	EI

General Comment:

[COGCC Environmental Inspection.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Tank battery signs stored at NE corner of battery were not installed on inspection date.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
Other	WELLHEAD	<= 1 bbl		
Comment:	Localized accumulations of oily waste observed at the following welheads: 17W, 15W, 13W, 11W, 9W, 7W, 6W, 8W, 10W, 12W, 4W, 3W, 1W, 1E, 2E, 4M, and 7M.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.			Date: 12/11/2019

In Containment: No

Comment: _____

☒ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Heated Separator	# 20		
Comment:	Twenty-four vertical heated separators on location. Scale buildup observed on 2" flowline riser on west side of separator labeled 29-09W, beneath hammer union. Salt staining observed on gravel in vicinity of 29-09W separator.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 11/26/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLS	STEEL AST		
Comment:	Tanks have conflicting NFPA labels on SE sides (Produced Water) and NW sides (Condensate/Produced Water).				
Corrective Action:	Correct signs to comply with Rule 210.d.				Date: 01/11/2020

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Comment:	No holes or tears were observed in visible portion of tank battery liner during inspection. Lined containment area contained fluids on inspection date. No hydrocarbon staining or sheens were observed on fluids.			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected Facilities				
Facility ID: 301474	Type: WELL	API Number: 077-09984	Status: PR	Insp. Status: EI
Facility ID: 301478	Type: WELL	API Number: 077-09988	Status: PR	Insp. Status: EI
Facility ID: 301481	Type: WELL	API Number: 077-09989	Status: PR	Insp. Status: EI
Facility ID: 301482	Type: WELL	API Number: 077-09990	Status: PR	Insp. Status: EI
Facility ID: 301483	Type: WELL	API Number: 077-09991	Status: PR	Insp. Status: EI
Facility ID: 301484	Type: WELL	API Number: 077-09992	Status: PR	Insp. Status: EI
Facility ID: 301485	Type: WELL	API Number: 077-09993	Status: PR	Insp. Status: EI
Facility ID: 301486	Type: WELL	API Number: 077-09994	Status: PR	Insp. Status: EI
Facility ID: 301487	Type: WELL	API Number: 077-09995	Status: PR	Insp. Status: EI
Facility ID: 301488	Type: WELL	API Number: 077-09996	Status: PR	Insp. Status: EI
Facility ID: 301489	Type: WELL	API Number: 077-09997	Status: PR	Insp. Status: EI
Facility ID: 301490	Type: WELL	API Number: 077-09998	Status: PR	Insp. Status: EI
Facility ID: 301491	Type: WELL	API Number: 077-09999	Status: PR	Insp. Status: EI
Facility ID: 301493	Type: WELL	API Number: 077-10001	Status: PR	Insp. Status: EI
Facility ID: 301494	Type: WELL	API Number: 077-10002	Status: PR	Insp. Status: EI
Facility ID: 301495	Type: WELL	API Number: 077-10003	Status: PR	Insp. Status: EI
Facility ID: 301496	Type: WELL	API Number: 077-10004	Status: PR	Insp. Status: EI
Facility ID: 301497	Type: WELL	API Number: 077-10005	Status: PR	Insp. Status: EI
Facility ID: 448318	Type: WELL	API Number: 077-10328	Status: PR	Insp. Status: EI

Inspector Name: Arauza, Steven

Facility ID:	448319	Type:	WELL	API Number:	077-10329	Status:	PR	Insp. Status:	EI
Facility ID:	448320	Type:	WELL	API Number:	077-10330	Status:	PR	Insp. Status:	EI
Facility ID:	448321	Type:	WELL	API Number:	077-10331	Status:	PR	Insp. Status:	EI
Facility ID:	448322	Type:	WELL	API Number:	077-10332	Status:	PR	Insp. Status:	EI
Facility ID:	448323	Type:	WELL	API Number:	077-10333	Status:	PR	Insp. Status:	EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698100090	20191108 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4985367