

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> KING ADDIE "M"	<b>Facility ID:</b> 118767
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> AMOCO PRODUCTION COMPANY / 2500	
<b>Updated Operator:</b> KP KAUFFMAN COMPANY INC - 46290	
<b>Form 15 Pit Permit Doc #:</b>	<b>Permit Date:</b>
<b>Related Facilities:</b> ADDIE M KING GAS UNIT TRUE #1 (API 05-123-11204)	

<b>County:</b> WELD			
<b>Township:</b> 1N	<b>Range:</b> 66W	<b>Section:</b> 4	<b>QQ:</b> SWNE
<b>Original Latitude/ Longitude:</b> 40.074698 / -104.779899			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #:                     | Date:            |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 664026             | Date: 8/13/1984  |
|                                     | Doc #: 200062432                                | Date: 10/26/2004 |
|                                     | Doc #:  | Date:            |
| <input checked="" type="checkbox"/> | Form 27 Remediation Workplan – Project #: 14070 | Date: 8/12/2019  |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:                   | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:                         | Date:            |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2142986                  | Date: 8/21/1997  |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:          |                  |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached)     |                  |
| <input type="checkbox"/>            | Other:  |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

No evidence of a pit on location. Well PA 8/6/2019

#### Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location. Pit inventory and inspection reports document a fiberglass tank on location; the fiberglass tank was removed under remediation project #14070. Pit status has been changed to Closed.

