

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: 03/10/1971

| Method used | String | Cementing tool setting/perf depth | Cement volume | Cement top | Cement bottom |
|-------------|--------|-----------------------------------|---------------|------------|---------------|
| DV TOOL | 1ST | 1,009 | 200 | | 1,009 |

Details of work:

03/10/71: DV tool @ 1,009'. Cemented Fox Hills with 200 sx Pozmix 2% gel.

FORMATION LOG INTERVALS AND TEST ZONES

| FORMATION NAME | Measured Depth | | Check if applies | | COMMENTS (All DST and Core Analysis must be submitted to COGCC) |
|----------------|----------------|--------|------------------|-------|---|
| | Top | Bottom | DST | Cored | |
| X BENTONITE | 6,639 | | | | |
| D SAND | 6,737 | | | | |
| J SAND | 6,802 | | | | |

Operator Comments:

This Form 5 is being submitted in response to a July 26, 2018 data request for a new Drilling Completion Report for wells that have not had one filed since 1999.

This well is a re-entry of the Amoco Production Company UPRR #29-1 well that was completed as an oil well on April 26, 1971.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Anthony P. Trinko

Title: Sr. Reservoir Engineer Date: 9/9/2019 Email: anthony_trinko@kindermorgan.com

Attachment Check List

| Att Doc Num | Document Name | attached ? | |
|------------------------------------|-----------------------|---|--|
| <u>Attachment Checklist</u> | | | |
| | CMT Summary * | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Core Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Directional Survey ** | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | DST Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Logs | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Other | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| <u>Other Attachments</u> | | | |
| 402169906 | FORM 5 SUBMITTED | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 402169927 | WELLBORE DIAGRAM | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|---------------------|---|---------------------|
| Engineering Tech | List of all logs run was edited Corrected 2nd string cement bottom to TD | 11/12/2019 |

Total: 1 comment(s)

