

Inspection Photos
Operator: BP America
Location/API #: 067-07139
Date: 11-6-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with smooth brome, intermediate wheatgrass, and sand dropseed.



Photo 3. View of reference area vegetation comprised of ponderosa pine forest and gambel oak understory with open grass fields.